

PlexusAV P-AVN-2

Firmware Version 1.2.1 Release Notes

June 20, 2025 - v1

Contents

Introduction.....	3
New features.....	4
Upgrade procedure	5
Upgrade with Local P-AVN-2 WebUI	6
Batch upgrade with Visual Array	8
Known issues	9

Introduction

This document covers firmware version 1.2.1 of the PlexusAV P-AVN-2 transceiver.

Important note:

- If you are using PlexusAV Visual Array, upgrade all P-AVN-2 units to firmware 1.2.1 first and then continue with the Visual Array 1.2.0 upgrade.

New features

- This is the initial firmware release of the P-AVN-2

Upgrade procedure


There are two ways to upgrade the P-AVN-2 firmware:

1. Using P-AVN-4 local WebUI
2. Using Visual Array: upgrading multiple P-AVN-2 units in one go


We will cover both ways of upgrading.

Upgrade with Local P-AVN-2 WebUI


Log into the unit and look for the ellipse on the right side of the web UI. Click it, then click “Update”.



Click the “Up-arrow” icon to open a window to select the update.




Select the update file and click “Open”. Then click “OK” to upgrade.



Batch upgrade with Visual Array


Select all transceivers in device list and go to “Advanced Settings”:




Delete any existing VA uploaded firmware (if there is any existing firmware) by clicking the bin button:



Click upload to upload the firmware to VA:



Update the units:




If all units are ready (100%), leave the advanced settings by clicking “Cancel”.

Known issues

- **Stream Conversion Gateway compatibility**

If the P-AVN-2 Decoder receives IPMX streams from the PlexusAV Stream Conversion Gateway, we recommend setting it to “Normal Latency” mode. If it is set to “Low Latency” you might experience occasional flickers or dropped frames.

You can set the P-AVN-2 “Normal Latency” mode by going to: “Dashboard”->“Video Output”->“Edit” and change to “Normal Latency”.



- **H.26x switching time**

Depending on video complexity, switching between H.26x streams can take between 2.5 and 3.5 seconds.

- **Precision Time Protocol (PTP) Time to Live (TTL)**

P-AVN-2 PTP packets have TTL=1, meaning that they will not be routable (between subnets / VLANs). We will increase the TTL to 255 in the next release. If you have an application that requires PTP routing now, please contact us.